NDCRS ARCHITECTURAL FORM
PAGE 1

UPDATE

Field Code _____ **SITS# 32 MN 1554**

Map Quad Stanley Site Name Cottonwood School
Map Quad _____ Site Name Hauglie School

LTL ___ **T.** 156 **N.**, **R.** 91 **W.**, **Sec.** 28 **QQQ** 6 ___ of the **QQ** 7 ___ of the **Q** 5 ___
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NAD 1983 UTM 5353724 Zone 13N
NAD _____ UTM 694164

City: Stanley

Street Number: 405

Street Name: 12th Ave SE

Urban Legal Description: Parcel # 61-0053600

Total Number of **Architectural** Features: 1

Fieldwork Date: _____

Reconnaissance Survey ✔ Intensive Survey _____

Project & Principal Investigator:

Contracting Firm or Agency Completing the Form:

SHSND

Additional Information:

The school is located in Flickertail Village. Site updated to correct sketch map and add information.

SHSND USE
Component _____ Study Unit _____ Verified Site _____ CR Type _____
Component _____
Component _____

Recorded By: E. Scherr, SHSND **Date Recorded:** 11/06/2025

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – *Feature Data*

UPDATE

Field Code _____ **SITS# 32** MN 1554

Complete one Page 2 for *each* architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date _____

Structural System _____

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context _____

Primary Exterior _____

Secondary Exterior _____

Condition _____

Plan Shape _____

Style _____

Architect/Builder _____

Foundation _____ Stories _____

Roof/Cornice _____

Window _____

Dating Method(s) _____

Miscellaneous Information _____

***Feature* Preservation Recommendation(s) (Check all that apply):**

_____Individual nomination

_____Contributes to a potential district

_____No nomination potential

_____Will not contribute to a district

_____Potential district—feature would be a contributing element if other properties constitute a district

_____Thematic nomination potential

_____Component of a historic site or landscape

_____Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

_____Historical associations require further investigation

Recorded By: E. Scherr, SHSND **Date Recorded:** 11/06/2025

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 3 – *Feature Data*

UPDATE

Field Code _____ **SITS# 32 MN 1554**

Complete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

No site visit. This update is to correct the sketch map and add information from the Flickertail Village site form (32MN633).

The Cottonwood/Hauglie School was recorded as Feature 13 in the Flickertail Village site form. The school will remain 32MN1554 and will be removed as a feature from the village site form.

2. Owner's Contact Information:

Recorded By: E. Scherr, SHSND **Date Recorded:** 11/06/2025

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code _____ **SITS# 32** MN_ 1554_____



Figure 1: 32MN1554 location within the Flickertail Village.

Recorded By: E. Scherr, SHSND **Date Recorded:** 11/7/2025

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL SITE FORM
page 2

Field Code BRW US2 S024 SITS # 32MN

13 Feature #	9 Feature Type	5 Condition
Construction Date	7 Context *	
3 Feature Date		5 Plan Shape *
25 Structural System **	26 Primary Exterior *	Secondary Exterior
0 Ethnic	14 Style	
10102100 Fieldwork Date		Architect/Builder
		Other Information

FOUNDATION TYPE: Concrete block

STORIES: 1

ROOF TYPE/CORNICE: Side gable; wood shingles

WINDOW CONDITION: Most original windows replaced/openings altered

DATING METHOD: Professional estimate

PRESERVATION RECOMMENDATION (check all that apply):

1) ____ Individual Nomination 2) ____ Contributes to a potential district
3) X No nomination potential 4) X Will not contribute to a district
5) ____ Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
6) ____ Thematic nomination potential 7) ____ Component of historic site/landscape

****

8) ____ Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
9) D Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
10) ____ Request comparative study of neighboring properties
11) ____ Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #13 is a rural schoolhouse from Cottonwood Township that has been moved into Flickertail Village. It is interpreted as a schoolhouse as part of the museum and is located at the end of the "Main Street." The one-story wood-frame building is rectangular in plan and has a concrete block foundation. The building is clad with horizontal wood siding with corner boards; the siding is not original. The side-gable roof is clad with wood shakes. The windows are primarily wood-framed double-hung, although all of the openings on the east facade have been filled in. The front one-third of the building appears to be an addition. It has a bell tower and a wood plaque that reads "Third Class Standard School". The school has been severely altered, including the in-filling of windows and the bell-tower addition; it is not known when the alterations took place.

The building retains little integrity. Furthermore, its removal from its original location has damaged its eligibility. The building does not meet any of the considerations under Criteria Consideration B.

Urban Legal Description

____ SEE CONTINUATION SHEET


NDCRS SITE FORM Photograph Field # BRW US2 S024 Site # 32MN

Photo I.D. Code BRW US2 Roll 28, Frame 23 (B&W); BRW US2 Roll 28, Frame 24 (B&W)
Storage Location State Historical Society of North Dakota: State Historic Preservation Office
Include direction facing, feature number, and photo caption for each submitted photograph.

Front of Country School #3 (Feature #13), facing NE



Rear of Country School #3 (Feature #13), facing SW



NDCRS SITE FORM Photograph Field # BRW US2 S024 Site # 32MN

Photo I.D. Code BRW US2 Roll 29, Frame 3 (B&W); BRW US2 Roll 28, Frame 25 (B&W)
Storage Location State Historical Society of North Dakota: State Historic Preservation Office
Include direction facing, feature number, and photo caption for each submitted photograph.

School Wagon (Feature #29), facing NW



Farm Equipment, facing NE



NDCRS *ARCHITECTURAL* SITE FORM

PAGE 1

Field Code Cottonwood School **SITS# 32** MN 1554

SITE IDENTIFICATION

Map Quad Stanley Site Name Cottonwood School

Map Quad _____ Site Name Hauglie School

LTL	TWP 156	R 91	SEC 28	QQQ 6	QQ 7	Q 5
LTL	TWP	R	SEC	QQQ	QQ	Q
LTL	TWP	R	SEC	QQQ	QQ	Q
LTL	TWP	R	SEC	QQQ	QQ	Q

NAD 1983, UTM 5353725 N **ZONE** 13N

NAD 1983, UTM 694165 E

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: Stanley

Street Number: 405

Street Name: 12th Ave SE

Urban Legal Description: _____

SITE DATA

Total # ***Architectural*** Features: 1

Fieldwork Date: 7/22/2019

Reconnaissance Survey ✔ Intensive Survey ___

Project & Principal Investigator:
Country Schoolhouse Project

Report Title & Author(s):

Contracting firm or Agency completing the form:

Additional Information:

SHSND USE

Area of Significance 2 Ecozone 21 Verified Site ___ CR Type 2

Area of Significance ___ Ecozone ___

Area of Significance ___ Ecozone ___

Recorded By Kathy Wilner **Date Recorded** 7/22/2019

(First Name & Last Name) **(mm/dd/year)**

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) ***Print*** and submit to SHSND.

NDCRS *ARCHITECTURAL* SITE FORM
PAGE 2—*Feature Data*

Field Code: Cottonwood School SITS# 32: MN

Complete one Page 2 for *each* architectural feature at the site.

Architectural Feature #: 1

Construction Date: _____ Feature Type: 9 Condition: 7

Feature Date: 3 Context: 7 Plan Shape: 5

Structural System: 25 Primary Exterior: 26 Style: Other Style

Original Owner's Ethnicity: _____ Secondary Exterior: N/A Architect/Builder: _____

Other Information: _____

Foundation: Concrete block Stories: 1

Roof/Cornice: Gable

Window: Double hung, glass intact

Dating Method(s): Estimate

***Feature* Preservation Recommendation(s) (Check all that apply):**

___ Individual nomination

___ Contributes to a potential district

___ No nomination potential

___ Will not contribute to a district

___ Potential district—feature would be a contributing element if other properties constitute a district

___ Thematic nomination potential

___ Component of a historic site or landscape

___ Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

___ Historical associations require further investigation

Recorded By: Kathy Wilner **Date Recorded:** 7/22/2019

(First Name & Last Name) **(mm/dd/year)**

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) ***Print*** and submit to SHSND.

NDCRS *ARCHITECTURAL* SITE FORM

PAGE 3—*Feature Data*

Field Code Cottonwood School SITS# 32 MN

Complete a Page 3 for each feature.

1. *Feature* Description, Integrity, Eligibility:

The feature, also known as Hauglie School, is a one room prairie school sitting on concrete block foundation. It was moved to this area to be part of a pioneer village. The gable roof of the building is covered with asphalt shingles. The original wood shakes were replaced in the 1990's. There is a bell tower at the peak of the roof at the southwest end of the school. The bell tower is roofed with asphalt shingles and there is a flag pole at the peak and a bell in the tower. Another large school bell sits on the ground at the entry corner of the school. The soffits are closed. The building measures 36 feet long by 16 1/2 feet wide.

A rake board begins the siding under the roof at the peak ends of the school. Remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. A new steel door, installed in 2019 to replace the old wood door, leads into the entry. A bank of 6 double hung vinyl windows are on the northwest wall. These windows replaced wood ones in 2018. All glass is intact and the windows have pull down shades with a curtain on the lower half. There is a double hung window in the entry and one more small, fixed pane window on the southeast side, also in the entry. Another door leads into the school proper. Blackboards fill the northeast and southeast walls inside the school. The walls are 4 inch wide wood boards running horizontally and this contines up the walls to ancurved finish, about a foot wide, to the beadboard ceiling. The floor is tongue and groove hardwood. There is no wainscote. There is electricity present. Heat was a coal stove. The school interior is much like it would have been when school was in session, complete with books, student desks, the teachers desk and much more.

Recorded By Kathy Wilner **Date Recorded** 7/22/2019

(First Name & Last Name) **(mm/dd/year)**

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) ***Print*** and submit to SHSND.

NDCRS *ARCHITECTURAL* SITE FORM
PAGE 4—*SITE DESCRIPTION*

Field Code Cottonwood School **SITS# 32** MN _____

Complete one Page 4 for the entire *site*.

2. Owner's Contact Information:
Flickertail Village Museum
405 12th Ave SE
Stanley ND 58784

3. Access (to rural areas):
Flickertail Village Museum is located in the town of Stanley. It is on the east side of town, north of Highway 2.

4. Site Area (**ft²**): _____

5. Description of ***SETTING***:
This school is located in a pioneer village with many buildings to the west, south and southwest. It is a grassed area with well cared for buildings.

Recorded By Kathy Wilner **Date Recorded** 7/22/2019
(First Name & Last Name) **(mm/dd/year)**

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) ***Print*** and submit to SHSND.

NDCRS *ARCHITECTURAL* SITE FORM
PAGE 5—*SITE DESCRIPTION*

Field Code Cottonwood School SITS# 32 MN

6. *Summary of ALL* Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418
Information and pictures for this school was submitted by Gerry Nelson with the Flickertail Village Museum.

Recorded By Kathy Wilner (First Name & Last Name) **Date Recorded** 7/22/2019 (mm/dd/year)


Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) ***Print*** and submit to SHSND.



North-
West
Side

Cottonwood School 7/22/2019 Kathy Wilner MN

North-
East
side






Southeast Side

Cottonwood School 7/22/2019 Kathy Wilner MN

South-west Side



Google Maps Cottonwood (Hauglie) School MN 7/22/2019 Kathy Wilner



Imagery ©2019 Google, Map data ©2019 50 ft