NDCRS ARCHITECTURAL FORM
PAGE 1

UPDATE

Field Code _____ **SITS# 32** **MZ** **445**

Map Quad _____ Site Name Sheep Butte School
Map Quad _____ Site Name _____

LTL ___ **T.** _____**N.**, **R.** _____**W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ___
LTL ___ **T.** _____**N.**, **R.** _____**W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ___
LTL ___ **T.** _____**N.**, **R.** _____**W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ___
LTL ___ **T.** _____**N.**, **R.** _____**W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ___

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NAD _____ UTM _____ Zone _____
NAD _____ UTM _____

City: _____

Street Number: _____

Street Name: _____

Urban Legal Description: _____

Total Number of **Architectural** Features: _____

Fieldwork Date: _____

Reconnaissance Survey _____ Intensive Survey _____

Project & Principal Investigator:

Contracting Firm or Agency Completing the Form:

SHSND

Additional Information:

Additional information provided by Harold Knutson's daughter Amy.

SHSND USE
Component _____ Study Unit _____ Verified Site _____ CR Type _____
Component _____
Component _____

Recorded By: **Lorna Meidinger** **Date Recorded:** **12/13/2024**

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 4 – *Site Description*

UPDATE

Field Code _____ **SITS# 32** MZ 445

3. Site Area (ft²):

4. Description of Access and Site Setting:

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Amy Knutson sent photos from the family collection to be added to the site file. Her husband's father, Harold Knutson, attended this school.

Recorded By: Lorna Meidinger **Date Recorded:** 12/13/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code _____ **SITS# 32** MZ 445



From Knutson Family Collection, taken 1951.

Recorded By: Lorna Meidinger **Date Recorded:** 12/13/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code _____ **SITS# 32** MZ 445



From Knutson Family Collection, taken 1951.

Recorded By: Lorna Meidinger **Date Recorded:** 12/13/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code _____ **SITS# 32** MZ 445



From Knutson Family Collection, taken 1941.

Recorded By: Lorna Meidinger **Date Recorded:** 12/13/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code _____ **SITS# 32** MZ 445



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code _____ **SITS# 32** MZ 445



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

UPDATE

NDCRS *ARCHITECTURAL* SITE FORM
PAGE 2—*Feature Data*

Field Code _____ **SITS# 32 MZ 445**

Complete one Page 2 for *each* architectural feature at the site.

Architectural Feature # 1-2

Construction Date _____ Feature Type _____ Condition 1

Feature Date _____ Context _____ Plan Shape _____

Structural System _____ Primary Exterior _____ Style _____

Original Owner's Ethnicity _____ Secondary Exterior _____ Architect/Builder _____

Other Information:

Based on 2009 aerial

Foundation _____ Stories _____

Window _____

Roof/Cornice _____

Dating Method(s): _____

***Feature* Preservation Recommendation(s) (Check all that apply):**

___ Individual nomination

___ Contributes to a potential district

___ No nomination potential

___ Will not contribute to a district

___ Potential district—feature would be a contributing element if other properties constitute a district

___ Thematic nomination potential

___ Component of a historic site or landscape

___ Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

___ Historical associations require further investigation

Recorded By Lorna Meidinger **Date Recorded** 9/16/2010

(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS SITE FORM
ARCHITECTURAL SITES

SITS # 32 (State) MZ (County) 00445 (Site Number)

Field Code Site Name
Field Code Site Name

Map Quad SATHER LAKE
Map Quad

LTL Twp 148 Range 103 Section 16 QQQ 8 QQ 8 Q 8

1. N 1/2
2. E 1/2
3. S 1/2
4. W 1/2
5. NE 1/4
6. SE 1/4
7. SW 1/4
8. NW 1/4
9. C

City:

Street # and Name

Street # and Name

# of Features 2

21	Soils	22	Ecozone	2	Area Signif		
0	Soils		Ecozone		Area Signif	J PURCELL	Coder
2	CR Type	1	Verified Site	0	Non-Site	8/13/1979	Date Coded
0	State Registry	0	National Register				Update

2 E C F 2 T F

1	Feature #	9	Feature Type	7	Condition
1925	Construction Date	7	Context		Integrity
	Feature Date			5	Plan Shape*
25	Structural System **	26	Primary Exterior *		Secondary Exterior
0	Ethnic	14	Style *		
06/00/78	Fieldwork Date		Fieldwork Date	0	Architect/Builder
			SCHOOL		Other Information

2	Feature #	50	Feature Type	7	Condition
0000	Construction Date	7	Context		Integrity
	Feature Date			5	Plan Shape*
25	Structural System **	26	Primary Exterior *		Secondary Exterior
0	Ethnic		Style *		
06/00/78	Fieldwork Date		Fieldwork Date	0	Architect/Builder
			OUTHOUSE		Other Information

NDCRS SITE FORM
HISTORICAL ARCHEOLOGICAL SITES

SITS # 32 MZ 00445
State County Site Number

Field Code Site Name
Field Code Site Name

Map Quad SATHER LAKE
Map Quad

LTL Twp 148 Range 103 Section 16 QQQ 8 QQ 8 Q 8

1. N 1/2
2. E 1/2
3. S 1/2
4. W 1/2
5. NE 1/4
6. SE 1/4
7. SW 1/4
8. NW 1/4
9. C

FEATURE TYPE

1 CM Scatter
0 Chimney
1 Depression
0 Dump
0 Earthworks
0 Fortification
1 Foundation
0 Graves
0 Hearth
0 Machinery
0 Quarry/Mine
0 Rock Art
0 Trail
0 Wreck
0 Other

CULTURAL MATERIAL

0 Bone
0 Ceramics
0 Charcoal
0 Cloth
0 Faunal Remains
0 Fire Cracked Rock
0 Floral Remains
1 Glass
0 Hide,Hair,Fur
0 Human Remains
0 Masonry
0 Metal
0 Plastic
0 Rubber
0 Shell
0 Wood
0 Other

9 SiteType
7 Context
0 SiteArea
m. x m.
0 Cultural Depth cm.
0 Depth Indicator

Occupation Date
Begin 1925
End 0

Basis for Dating 3

0 CM Density
0 Isolated Find

Landform 1 18 Landform 2 Slope/Exposure 7 Ecosystem
Landform 1 Landform 2 Slope/Exposure Ecosystem

Elevation: 700 m.
Drainage System YELLOWSTONE RIVER
View, Degree
View, Distance

Dist Perm Water 20 m.
Perm Water Type 2
Dist Seas Water 0 m.
Seas Water Type 0

1 Ownership
Ownership

06/01/78 Fieldwork Date
Fieldwork Date

Site Condition
1 Collection
Test/Probe
Excavation

Additional Information
2 Management Recommendation

21 Soils 22 Ecozone 3 Area Signif
0 Soils Ecozone Area Signif

2 CR Type 1 Verified Site 0 Non-Site
2 E C F 2 T F
J PURCELL Coder
8/13/1979 DateCoded

0 State Registry 3 National Register
Update

NORTH DAKOTA CULTURAL RESOURCES SURVEY

Base Data Form

1. County McKenzie 2. Site Number 32MZ445
3. Site Name (s) _____
4. Type of Resource: A. Archaeological__ Historical X Architectural__ Paleontological__
   B. District__ Site__ Building X Structure__ Object__
5. Map Reference: U.S.G.S. Sather Lake, 7.5' Quad. (1972)
6. Location: NW¼, NW¼, NW¼ Sec. 16 T 148 N / R 103 W
   Plat: _____ Block _____ Lot _____
   UTMG: A. _____ B. _____
   C. _____ D. _____
7. Access: Travel south of Highway 68 for 2 miles and west along the section line road about 0.6 mile to the building.
8. A. General description of site: Site is a standing and abandoned schoolhouse. There are the remains of some outbuildings which were probably associated with the school. Building still in excellent condition.
   B. Condition of site: Excellent
9. Owner's name/address: Located on a school section (State of N.D.)
10. Occupant's name/address: Probably grazed.
11. Historic Register value: Nat.* State__ Undt.__ None__ On Reg.__ In District__ District__
12. Open to public: Yes X No__ 13. Preservation Underway: Yes__ No X
14. Endangered by: Possible looting or fires.
15. Survey Project: Title Little Missouri - 110 Sites Director L. Loendorf
    Other surveys in which included None
16. Recommendations: Should be preserved through documentation. Historical research should be done to learn the age.
17. Environment: Elevation 2306' Nearest Water: Type Spring fed stream
    Name Unknown Distance 20 meters Direction East
    Soil conditions: Prairie sod with developed subsoils
    Soil Texture: Loosely compacted

*The site meets the criteria as stated.

MS 299

Site Number 32MZ445

17. Environment, Cont.

Ground Cover: Deciduous trees along the creek.

Terrain: Flat prairie adjacent to flowing stream.

18. Local contact person or organization: U.S. Forest Service

19. Photos: No__B/W__Color__Prints__Slides X Comments/ID code


Labeled with the site number.

Negatives stored at: University of North Dakota Archaeological Research

In space below attach and identify a picture or contact print of the site.

20. Sketch Map of Site: Scale:

SEE Page 5.



Recorded by: Lawrence L. Loendorf Date 6/78

Revised by: Date

27. Thematic category Pioneer schoolhouse 28. Date or period 1925 (?)

29. Structures: Number standing Two Number collapsed One
Number of foundations only One Number of earthworks Zero
Number of basement depressions Zero No structural remains observed Three

30. Architectural/Structural Detail: (Also see continuation sheet - page 4)

A. Style or design Rectangular frame building

B. Architect/engineer Unknown

C. Contractor/builder Unknown

D. Original use School house

E. Present use Abandoned

F. Number of stories 1 plus attic G. Basement: Yes No X Partial

H. Foundation Material Rock - mortared

I. Wall Construction Wood frame with wood siding

J. Wall Treatment All building is frame

K. Roof type and material Shingle on peaked roof

L. Number of bays: Front 0 Side 0 M. Plan shape Rectangular

31. Frontage West 32. Distance from road 15 meters

33. Number of outbuildings 2 34. Description of outbuildings
One, two stall outhouse about 5 meters east of school building; another rock foundation about 11 meters southeast of southeast corner of school (woodshed ?)

35. Changes None evident

36. Information sources/References None

37. Reason for significance: Building is still attractive and in good condition.

Recorded by Lawrence L. Loendorf Date 6/78
Revised by Date

NORTH DAKOTA ARCHAEOLOGICAL SURVEY
CONTINUATION SHEET

SITE NO. 32MZ445 LOCATION NW¼,NW¼,NW¼ SEC. 16 T. 148N R. 103W

NAME _____ DATE 6/78


Building is still standing and in good condition. Roof is peaked about 20 feet high. Building is 25' X 15' and sitting on a rock - mortar foundation.


North side has 5, 3' X 5' windows. South and east sides have no windows. Door and two side windows on west side. Door is 3' X 8' with two small 1½' X 1' windows over it. Door is gone - frame remains. Two windows are 2' X 2'.

Small cupboard in the southwest corner. Coat hooks along the west side.

Chimney and wood burning potbelly stove to the south of center near the east wall. Chimney center of east wall.

All construction frame - floor is frame. Ceiling gone - once at 10'. The bell tower is still on west side. Frame and tin square temple type top. Flat post still off the top.


Sather Lake
Riser
2267
SPILLWAY
2261
Sather Lake
Recreation Area
Horse
Creek
Well
Well
2342
2530
2377
2341
2367
2324
2306
2305
2383
2409
2412
Sheep
Butte
2705
32MZ945
Sather Lake Quad
(1972)



might still be there

Tuesday, Dec 09, 2008 08:33 AM