NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code LakevilleTownshipSchool **SITS# 32** BK 386

Map Quad Northgate Site Name Lakeview Township School
Map Quad _____ Site Name _____

LTL ___ **T.** 163 **N.**, **R.** 89 **W.**, **Sec.** 31 **QQQ** 5 of the **QQ** 6 of the **Q** 5
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NAD 1983 UTM 5420319 Zone 13N
NAD 1983 UTM 700581

City: _____

Street Number: _____

Street Name: County Road 8 or 71st Ave NW

Urban Legal Description: _____

Total Number of **Architectural** Features: 1

Fieldwork Date: 04/12/2024

Reconnaissance Survey ✔ Intensive Survey _____

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE Bowdon, ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
Component 2 Study Unit 20 Verified Site 1 CR Type 2
Component _____
Component _____

Recorded By: Kathy Wilner **Date Recorded:** 04/22/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – *Feature Data*

Field Code LakevilleTownshipSchool **SITS# 32** BK 386

Complete one Page 2 for *each* architectural feature at the site.

Architectural Feature # 1

Construction Date

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity

Feature Type 9 - School; Church school

Context Education

Primary Exterior Metal, Sheet

Secondary Exterior

Condition Excellent

Plan Shape Rectangular

Style Other Style

Architect/Builder

Foundation Poured concrete Stories 1.0

Roof/Cornice Gable

Window Replacement windows with glass

Dating Method(s) Estimate

Miscellaneous Information

***Feature* Preservation Recommendation(s) (Check all that apply):**

_____Individual nomination

_____Contributes to a potential district

_____No nomination potential

_____Will not contribute to a district

_____Potential district—feature would be a contributing element if other properties constitute a district

_____Thematic nomination potential

_____Component of a historic site or landscape

_____Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

_____Historical associations require further investigation

Recorded By: Kathy Wilner **Date Recorded:** 04/22/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 3 – *Feature Data*

Field Code LakevilleTownshipSchool **SITS# 32** BK 386

Complete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature is a one room school moved to this location and place on a poured concrete foundation. The gable roof of the building is covered with white metal sheeting. There is no chimney. The soffits are open.

The sides of the school are all covered with red metal sheeting. The siding was put on the school in 2009. There are two replacement windows on the west side of the school. Two more similar windows are located either side of the entry door on the north side of the building. The replacement entry door has glass in the top half. Entering the school there is a small room to the right, likely a coat room. There is another small room to the left. The floor of the school is tongue and groove hardwood. The walls are a mixture of lathe and plaster and sheetrock. The ceiling is wallboard. Wainscot runs under the windows. Hanging white globe lights indicate electricity is present.

The school was moved to the farm to be used as a small implement business which opened in 1969.

2. Owner's Contact Information:

Joanne & Kim Sorum
4 Madison St.
Bowbells, ND 58721

Recorded By: Kathy Wilner **Date Recorded:** 04/22/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 4 – *Site Description*

Field Code LakevilleTownshipSchool **SITS# 32** BK 386

3. Site Area (ft²):

4. Description of Access and Site Setting:

This schools is located about 7 miles north of Bowbells. Go north out of Bowbells on Hwy. 52, the road will curve to the west. Go one mile past the curve to turn north on County Road 8 (71st Ave NW). Go 3/4 of a mile north to see the farm on the left (west). The school is sitting near the south side of the farm yard. It is set amidst farm buildings with farm land all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Information and pictures were provided by Joanne and Kim Sorum.
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 04/22/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



West Side

Lakeview Township School 4/12/2024 Kathy Wilner BK

South Side





North Side

Lakeview Township School 4/12/2024 Kathy Wilner BK

East Side



Google Maps Lakeview Township School 4/12/2024 Kathy Wilner BK



Imagery ©2024 CNES / Airbus, Maxar Technologies, USDA/FPAC/GEO, Map data ©2024 200 ft

Feature