NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code Estherville School **SITS# 32** BL 1285

Map Quad Regan Site Name Estherville School
Map Quad _____ Site Name _____

LTL ___ **T.** 143 **N.**, **R.** 78 **W.**, **Sec.** 9 **QQQ** 5 of the **QQ** 8 of the **Q** 8
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ____ of the **QQ** ____ of the **Q** ____

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NAD 1983 UTM 5231857 Zone 14N
NAD _____ UTM 380644

City: Regan

Street Number: 13487

Street Name: 383rd Ave NE

Urban Legal Description: _____

Total Number of **Architectural** Features: 1

Fieldwork Date: 06/10/2025

Reconnaissance Survey ✔ Intensive Survey _____

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
Component 2 Study Unit 19 Verified Site _____ CR Type 2
Component _____
Component _____

Recorded By: Kathy Wilner **Date Recorded:** 08/06/2025

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – *Feature Data*

Field Code Estherville School **SITS# 32** BL

Complete one Page 2 for *each* architectural feature at the site.

Architectural Feature # 1

Construction Date 1894

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity

Feature Type 9 - School; Church school

Context Education

Primary Exterior Metal, Sheet

Secondary Exterior

Condition Excellent

Plan Shape Rectangular

Style Other Style

Architect/Builder

Foundation Concrete Stories 1.0

Roof/Cornice Gable

Window New Side Slider

Dating Method(s) date from the owner

Miscellaneous Information

***Feature* Preservation Recommendation(s) (Check all that apply):**

_____Individual nomination

_____Contributes to a potential district

_____No nomination potential

_____Will not contribute to a district

_____Potential district—feature would be a contributing element if other properties constitute a district

_____Thematic nomination potential

_____Component of a historic site or landscape

_____Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

✔ Historical associations require further investigation

Recorded By: Kathy Wilner **Date Recorded:** 08/06/2025

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 3 – *Feature Data*

Field Code Estherville School **SITS# 32** BL

Complete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature is a one room prairie school that was moved to this location in the mid 1960's to be used for storage. The original location was about 1 mile south. It is sitting on a concrete foundation. The roof has been covered with grey metal sheeting. There is a metal chimney located at the northwest corner of the roof. The soffits are closed. The building measures 30 feet north to south and 18 feet east to west.

The siding is red metal sheeting. A wood rake board is seen just under the eaves at the north and south ends of the school. It was installed over the original wood lap siding as a means to preserve the building. There are two new side sliding windows on the north and two similar windows on the south. None of the original windows exist anymore. The entry door is a new solid core door with a screened exterior door. The interior was entirely gutted. The owner put grooved 4x8 sheets of plywood on all the walls and ceiling inside the school. The floor is new vinyl planking. There are no blackboards remaining and no wainscot. There is electricity and the building had a wood stove for heat. This building is used as a cabin today.

2. Owner's Contact Information:

Kerby Hausauer
13487 383rd Ave NE
Regan ND 58477

Recorded By: Kathy Wilner **Date Recorded:** 08/06/2025

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 4 – *Site Description*

Field Code Estherville School **SITS# 32** BL

3. Site Area (ft²):

4. Description of Access and Site Setting:

Located northwest of Regan. Situated near the road on a farm. Farm bins and buildings across the road to the north and more to the south. Many trees have been planted on the east, west, and south sides of the farmyard. To reach the school, travel from Hwy36 at Regan. Follow RR Ave W west into the curve that becomes 158th St NE. In 2 miles turn left on 344th Ave NE and go 1 mile. Turn right on 145th St NE and drive 3 miles to 383rd Ave NW. Turn left & follow road about 3/4 mile. School is on the left.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 08/06/2025

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South Side

Estherville School 6-10-2025 Kathy Wilner BL

West Side





East Side

Estherville School 6/10-2025 Kathy Wilner BL



Estherville School 6-10-2025 Kathy Wilner BL

