NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code _____ **SITS# 32 MH 517**

Map Quad Bergen Site Name Hendrickson Township School
Map Quad _____ Site Name _____

LTL ___ **T.** 154 **N.**, **R.** 78 **W.**, **Sec.** 32 **QQQ** 6 ___ of the **QQ** 5 ___ of the **Q** 6 ___
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ___ of the **QQ** ___ of the **Q** ___
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ___ of the **QQ** ___ of the **Q** ___
LTL ___ **T.** _____ **N.**, **R.** _____ **W.**, **Sec.** _____ **QQQ** ___ of the **QQ** ___ of the **Q** ___

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NAD 1983 UTM 5330384 Zone 14N
NAD 1983 UTM 372487

City: Karlsruhe

Street Number: _____

Street Name: 6th Ave N

Urban Legal Description: _____

Total Number of **Architectural** Features: 1

Fieldwork Date: 06/16/2024

Reconnaissance Survey ✔ Intensive Survey _____

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE Bowdon, ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
Component 2 Study Unit 20 Verified Site 1 CR Type 2
Component _____
Component _____

Recorded By: Kathy Wilner **Date Recorded:** 06/19/2024

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – *Feature Data*

Field Code _____ **SITS# 32 MH 517**

Complete one Page 2 for *each* architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Excellent

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Poured Concrete Stories 1.0

Roof/Cornice Gable

Window Double hung with glass intact

Dating Method(s) Estimate

Miscellaneous Information _____

***Feature* Preservation Recommendation(s) (Check all that apply):**

_____Individual nomination

_____Contributes to a potential district

_____No nomination potential

_____Will not contribute to a district

_____Potential district—feature would be a contributing element if other properties constitute a district

_____Thematic nomination potential

_____Component of a historic site or landscape

_____Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

_____Historical associations require further investigation

Recorded By: **Kathy Wilner** **Date Recorded:** **06/19/2024**

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 3 – *Feature Data*

Field Code _____ **SITS# 32** **MH** **517**

Complete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room school moved to this location and placed on a poured concrete foundation. The gable roof is covered with metal sheeting with a chimney located at the west end near the peak. The soffits are open. The school measures 16 feet from north to south by 40 feet east to west.

The siding begins with a rake board under the eaves at the peak ends of the school. The remainder of the siding is 6 inch wood lap with 4 inch wood corner trim. The is no entry on the building. There is a newer solid core door with a storm door located on the west end of the building. The school has several double hung (Roscoe Storm) windows with glass intact. There is a bank of 6 windows on the south wall, a single window located on the south wall near the west end and similar window located on the west end of the north wall. The single windows were for light in the coat room and/or the stairway to the basement when it was in its previous location. Two more windows are located near the east side near the south wall. The interior has wallboard on both the ceiling and walls. The floor is hardwood. There is no blackboard. The building has electricity evidenced by wiring on the west exterior wall near the entry door. The building was heated by a coal stove.

The building was purchased in 1961 for $250 and moved to its present location. They also purchased the outdoor toilet for $5. The building was used as a home for a couple and their four children. They partitioned off part of the east end for a bedroom. They never had running water in the building.

2. Owner's Contact Information:

Sandra Duchsherer
PO Box 207
Granville ND 58741

Recorded By: **Kathy Wilner** **Date Recorded:** **06/19/2024**

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 4 – *Site Description*

Field Code _____ **SITS# 32 MH 517**

3. Site Area (ft²):

4. Description of Access and Site Setting:

This school is located on a farm. It was moved to this location for use as a home. The school is at the south edge of a farm yard with buildings and trees to the north and west. There is a farm to the north and another to the northwest. Fields go in all directions. To reach this school from Highway 52, between Balfour and Bergen, go north (through Karlsruhe) on 48th St about 9 1/4 miles. Look for 48th St N, turn left and go west 4 miles to 6th Ave N. Turn right onto 6th Ave N and go about 1/3 mile north, the farm is on your left.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Photos and information shared by Sandra Duchsherer.
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: **Kathy Wilner** **Date Recorded:** **06/19/2024**

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South Side

Hendrickson Township School 6/16 2024 Kathy Wilner MH

South Side
and East Side





West Side

Hendrickson Township School 6/16/2024 Kathy Wilner MH

Google Maps Hendrickson Township School 6/18/2024 Kathy Wilner MH

1/1



Imagery ©2024 CNES / Airbus, Maxar Technologies, USDA/FPAC/GEO, Map data ©2024 200 ft